

QSW - Quasi Sine Wave from Sterling Alt  
 FSW - Full Sine Wave



Contactor - 48 A from generator



Contactor - 20 A from other sources



Mechanical interlock

